ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
I1089, W1069, W0734, W1295, W1281	NA	Rajivgandhi Nagar
Segment No.	**Total Length (m)**	
3/C-I1089/S043734	59.40	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	6.91	77.545666	13.085645	77.545729	13.085654	W0734	W0734
2	6.73	77.546270	13.085739	77.546330	13.085753	W0734	W0734
3	45.76	77.542829	13.087452	77.543169	13.087212	W1065	W1069

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Concrete Drain and Concrete Roads at Rajivgandhi Nagar in wards no 03 Yelahanka Satellite Town Sub division Yelahanka zone	1056000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Construction of Concrete Drain and Concrete Roads at Rajivgandhi Nagar in wards no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-16-000028
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D) /WO/109/2016 -17	07/01/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/02/2017	27/02/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		CHANDRAKANTH
Date of Inspection	**Remarks**	
19/03/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: I1089, W1069, W0734, W1295,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	18/04/2017	COMPLETED
SE	VASU K M	19/03/2017	18/04/2017	COMPLETED
EE	VASU K M	19/03/2017	18/04/2017	COMPLETED
AEE	ASHOK	19/03/2017	18/04/2017	COMPLETED
AE	CHANDRAKANTH	19/03/2017	18/04/2017	COMPLETED
AE	CHANDRAKANTH	19/03/2017	18/04/2017	COMPLETED

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: I1089, W1069, W0734, W1295,